

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




Fig. 1






Fig. 2



**Fig. 3**



**Fig. 4**




Fig. 5




Fig. 6







Fig. 7




**Fig. 8**




**Fig. 9**




**Fig. 10**




**Fig. 11**




**Fig. 12**




**Fig. 13(a)**



**Fig. 13(b)**



*Fig. 14(a)*



*Fig. 14(b)*





Fig. 15(b)







Fig. 16(b)




Title: SEAT BELT DEVICE  
Inventor(s): James G. STANLEY  
et al.  
DOCKET NO.: 086142-0599




*Fig. 17*




*Fig. 18*




*Fig. 20*




*Fig. 19*




*Fig. 21(a)*




*Fig. 21(b)*



*Fig. 22(a)*



*Fig. 22(b)*



*Fig. 22(c)*




Fig. 23




Fig. 24




Fig. 25




Fig. 26








Fig. 28(a)




Fig. 28(b)

**PRIOR ART**




Fig. 29





Fig. 30

PRIOR ART



*Fig. 31*

**PRIOR ART**